

Sample Report



Photo 1. This is the front (north elevation).



Photo 2. This is the cracked attic rafter.

Sample Report



Photo 3. The main water supply pipe is blocking the furnace filter.



Photo 4. There is no overflow pan under the second floor furnace. *This may cause a water leak in the ceiling below.*

Sample Report



Photo 5. The downspout is disconnected and discharging alongside the foundation. *This may cause basement flooding.*



Photo 6. There are numerous worn shingles on the south elevation. *This may cause a roof leak.*

*End of photos*